

1/31

FIG. 1

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print Mail

Address <http://sitedevelopment.geoneering.com/e/signup.html> Go Links

BRYANT CONSULTANTS

124 ~ [LOG IN]
126 ~ [GEONEERING HOME PAGE]

REGISTRATION

Usage of this system is restricted to those individuals and companies approved by Bryant Consultants, Inc. If you would like an account, please fill in the form below, indicate your acceptance of the User Agreement, and click "Submit".

102

Name: (First) (MI) (Last)

Company Name: 108

Address: 110

City, State, ZIP: 114

Company Web Site: http:// 116

Your Email: 118

Phone Number: 120

User Agreement: 122

Bryant Consultants, Inc., and Earthsystems Technologies are all in and of the same company. For the purposes of this User Agreement and Privacy Statement, Bryant Consultants, Inc. will represent by both entities.

Scope

This Terms of Use of Earthsystems Technologies, Inc. Content ("Agreement") is applicable to any content that is provided by Earthsystems Technologies, Inc. that you access by virtue of the Web site from which you are accessing this




FIG. 2

3/31





FIG. 3



5/31

500

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back

Forward

Stop

Home

Search

Media

Print

Stop

Reload

Go

Address Links

B R Y A N T
CONSULTANTS

306 ~ [PROJECT ADMIN]

308 ~ [GEONEERING]

310 ~ [CONTACT ADMIN]

312 ~ [GEONEERING OVERVIEW]

314 ~ [LOG OUT]

Project Name: Providence Phase I

Start Date:

End Date:

510 Save project

512 Back to Project Admin

514 Work with this project

Audit Info

Created: 11/12/02 11:38:30 17 - demo

Updated: -

FIG. 5

6/31

FIG. 6

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print Mail Address <http://sitedevelopment.geoneering.com/e/contactadmin.html?stateInfo=eLHcEjtaC8BdaYq8833> | 8 Go Links

BRYANT CONSULTANTS

312 ~ [GEONEERING OVERVIEW] 314 ~ [LOG OUT]

306 ~ [PROJECT ADMIN] 614

608 308 ~ [GEONEERING]

General Contacts Project Contacts

This is your general list of contacts. Each of these people may serve in one or more roles in any of your projects. Select one of your contacts to edit, or click "New" to add a new contact.

Name	Company	Email	Phone	616
Bond, James	Britts Intell	jbond@007.com	555-555-5555	NEW
Smith, John	Smith Company	jsmith@smithco.com	555-555-5555	
Richards, Ben	Richards Engineers	brichards@richards.com	555-555-5555	
Hoffa, Jimmy	Site Concrete		555-555-5555	
Jones, Basketball	Hoop it up	bjones@hoop.net	555-555-5555	
Fraser, Dave	US Homes	dfraser@ushomes.com	555-555-5555	
Thirwell, Kevin	City of Dallas		555-555-5555	
Quest, John	Quest Engineering	jquest@quest.com	555-555-5555	
Jack, Ripper	Cutting Edge Technologies	jripper@oj.com	555-555-5555	
Tracy, Dick	Tracy Investigations	dtracy@thetracy.com	555-555-5555	602
				604

7/31

700

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Media Print Favorites Home

Address http://sitedevelopment.geoneering.com/e/mt_clientcontacts.html?rowid=0X0000060e6&stateInfo=eLHcEJjacBbdaYq8833 Go Links

BRYANT
CONSULTANTS

306 ~ [PROJECT ADMIN] 310 ~ [CONTACT ADMIN]

308 ~ [GEONEERING] 312 ~ [GEONEERING OVERVIEW]

314 ~ [LOG OUT]

Last Name: 704

First Name: 702

Company: 706

Email: 708

Phone: 710

712 714 716

Audit Info

Created: 10/31/02 11:10:37 15 -

Updated: -

FIG. 7

8/31

800

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print Mail

Address <http://sitedevelopment.geoneering.com/e/project.html> Go Links

BRYANT CONSULTANTS

Contact Administration 306 ~ [PROJECT ADMIN] 312 ~ [GEONEERING OVERVIEW]
 Project: Swampland Estates Phase I [!] 308 ~ [GEONEERING] 314 ~ [LOG OUT]

General Contacts Project Contacts

This is a list of contacts that apply to the project: "Swampland Estates Phase I"
 You should select a contact for each role. If you need to define a new contact to show up in one of the pull-down lists, click the "General Contacts" tab.

Environmental:	<input checked="" type="radio"/> Bond, James - Brits Intell	<input type="button" value="v"/>	802 ~ <input type="radio"/> Unknown for now
Civil:	<input checked="" type="radio"/> Hoffa, Jimmy - Site Concrete	<input type="button" value="v"/>	<input type="radio"/> Unknown for now
Geotechnical:	<input checked="" type="radio"/> Quest, John - Quest Engineering	<input type="button" value="v"/>	<input type="radio"/> Unknown for now
Structural:	<input checked="" type="radio"/> Ripper, Jack - Cutting Edge Technologies	<input type="button" value="v"/>	<input type="radio"/> Unknown for now
Land Developer:	<input checked="" type="radio"/> Tracy, Dick - Tracy Investigations	<input type="button" value="v"/>	<input type="radio"/> Unknown for now
Site Development:	<input checked="" type="radio"/> Smith, John - Smith Company	<input type="button" value="v"/>	<input type="radio"/> Unknown for now

814 ~

FIG. 8

9/31




FIG. 9

10/31

FIG. 10

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print Address http://sitedevelopment.geoneering.com/e/geoneering.html?tab=Civil&stateInfo=eLHcEjtacBbdajYq8833|14 Go Links

1000

BRYANT CONSULTANTS

Geoneering
Project: Swampland Estates Phase I [!]

306 ~ [PROJECT ADMIN]
310 ~ [CONTACT ADMIN]
312 ~ [GEONEERING OVERVIEW]
314 ~ [LOG OUT]

Risks Civil Site Development Environmental Geotechnical Structural

Have you participated in an early development, pre-construction meeting to evaluate potential civil site challenges? [More Info](#) ~ 1004

1006 ~ Yes ☒ No ☐
1010 ~ Don't know ☐ Skip for now ☐

Has the civil engineer provided positive grades on each of the building lots? [More Info](#) ~ 1004

1006 ~ Yes ☒ No ☐
1010 ~ Don't know ☐ Skip for now ☐

Has a sufficient pad design been done to avoid excessive cut and fill beneath the building pads? [More Info](#) ~ 1004

1006 ~ Yes ☒ No ☐
1010 ~ Don't know ☐ Skip for now ☐

11/31




FIG. 11

12/31




FIG. 12

13/31




FIG. 13

14/31

1900

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Media Print Favorites Home

Address http://sitedevelopment.geoneering.com/e/mt_settings.html?rowid=0x00005d80&stateInfo=eLHcE|tacBbdajYq88833|25 Go Links

BRYANT CONSULTANTS

MAINTAIN SYSTEM SETTINGS

1908 ~ [ADMIN MAIN MENU]
1910 ~ [LOG OUT]

1912 ~ Account ID: *

1914 ~ ID Type: All

1916 ~ Setting Type: General

1918 ~ Setting Name: Session Timeout Period

1920 ~ Setting Value: 3600

1922 ~ Setting Description: Number of seconds to keep a web user's session active while waiting for a response from them. If the user simply goes away without hitting the site for too long, their session will be

1902 ~ Submit

1906 ~ Back to List of Settings

1904 ~ Delete

1928 ~ Audit Info

Created: 8/17/00 15:12:45 Web User - ?

Updated: 11/04/02 12:54:34 2 -

1908 ~ [ADMIN MAIN MENU] [LOG OUT] ~ 1910

FIG. 14

15/31




FIG. 15

16/31

2100

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Media Favorites Search Go Links

Address http://sitedevelopment.geoneering.com/e/mt_clients.html?rowid=0x00005de38&stateInfo=eLHcEjtacBbdajYq8833|29

B R Y A N T
CONSULTANTS

Maintain System clients

2112

2116 ~ Client ID:

2118 ~ Client Name:

4 (Automatically assigned)

Smith Company

2102

2104

2106

Submit

Delete

Back to List of Clients

Audit Info

Created: 10/28/02 17:06:11 2 -

Updated: -

1802 ~ [ADMIN MAIN MENU]

314 ~ [LOG OUT]

2108 ~ [ADMIN MAIN MENU] [LOG OUT] ~ 2110

FIG. 16




FIG. 17

18/31

2300

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help


Back Home Search Favorites Media Print Mail

Address http://sitedevelopment.geoneering.com/e/mt_siteusers.html?rowid=0X000Dec82&stateInfo=eLHcEjacBbdaYq8833 32 Go Links

**B R Y A N T
CONSULTANTS**

Maintain System Users

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

2332 

2314 ~ User ID: 17 (Automatically assigned)

2316 ~ User Name: demo (Login ID)

2318 ~ Password: qhbaenldxDkMyYcj (Encoded - not actual password)

2320 ~ Start Date: ? (MM/DD/YY)

2322 ~ End Date: ? (MM/DD/YY)

2324 ~ Admin User: ☐ (Check this box to make the user an admin user!)

2326 ~ Client: 8- Demo ☒ [Maintain Client List]

2328 ~ Failure Count: 0 (Reset to zero if user is locked out!)

2330 ~ Phone: 0

2302 ~ Submit 2304 Delete

2306 ~ Back to List of Users 2312

Audit Info

Created: 11/12/02 11:05:02 5 - kzjones


Updated: 11/12/02 10:59:32 14 - mgehrig

2308 ~ [ADMIN MAIN MENU] [LOG OUT] ~ 2310

FIG. 18

19/31

FIG. 19



20/31

FIG. 20

2500

Site Administration - Microsoft Internet Explorer
File Edit View Favorites Tools Help
Back Forward Stop Search Media Favorites Links
Address http://sitedevelopment.geoneering.com/e/mt_questions.html?rowid=0X0000e0a0&stateInfo=eLHcE[acBbdajYq8833|36] Go

**B R Y A N T
CONSULTANTS**

Maintain Questions

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]


2514 ~ Question ID: 37 (Automatically assigned)
2516 ~ Question Area: Civil
2518 ~ Sort Order: 0 (Within the area selected)
2520 ~ Question Text: Have you participated in an early development, pre-construction meeting to evaluate potential civil site challenges?
2522 ~ Action URL: More Info
2524 2526 2528 2530
Risks: Yes: 0 No: 102 Skip: 0 DK: 103 [View Risk List...]
2532 ~ Executable: procs/mailto, p (User relative path)

2502 ~ Submit 2504 Delete
2506 ~ Back to List of Questions 2512
Audit Info
Created: 11/12/02 09:14:25 2 -
Updated: 11/12/02 09:15:40 2 -

2508 ~ [ADMIN MAIN MENU] [LOG OUT] ~ 2510

21/31

FIG. 21



22/31

FIG. 22

2700

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Home Search Favorites Media Print Address http://sitedevelopment.geoneering.com/e/mit_risks.html?rowid=0x000051e47stateInfo=eLHcEjtacBbdaYq8833|39 Go Links

BRYANT CONSULTANTS

Maintain Risks

1802 ~ [ADMIN MAIN MENU] 314 ~ [LOG OUT]

2714 ~ Risk ID: 102 (Automatically assigned)

2716 ~ Risk Area: Civil

2718 ~ Sort ID: 0 (Within the area selected)

2720 ~ Risk Text: Setup up a meeting with all interested parties on civil engineering site challenges

2722 ~ Action URL:

2724 ~ Distributing List: E,C,G,S,D enter role codes E,C,G,S,D

2706 ~ Submit 2708 ~ Delete

2710 ~ Back to List of Risks 2712 ~ Audit Info


Created: 10/30/02 07:39:18 2 -

Updated: 10/3 Audit fields are automatically maintained

[ADMIN MAIN MENU] [LOG OUT]

23/31

FIG. 23



2900

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print

Address http://sitedevelopment.geoneering.com/e/mt_contacts.html?rowid=0x000060e6&stateInfo=eLHcEltacBbdajYq8833 | 42 Go Links

BRyant
CONSULTANTS

Maintain System Contacts

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

16 (Automatically Assigned)

8 - Demo [Maintain Client List]

Smith

John

Smith Consultants

john@geoneering.com

555-5555-5555

2912 ~ Contact ID:
2914 ~ Client:
2916 ~ Last Name:
2918 ~ First Name:
2920 ~ Company:
2922 ~ Email:
2924 ~ Phone:

2906 ~ Submit Delete 2908

2910 ~ Back to List of Contacts

Audit Info

Created: 10/31/02 11:10:37 15 -

Updated: -

[ADMIN MAIN MENU] [LOG OUT]

FIG. 24

25/31

3000

Site Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print Links

Address http://sitedevelopment.geoneering.com/e/brws_eventlogs.html Go

BRYANT CONSULTANTS

System Events

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

Starting: 10/27/02 3002

Ending: 11/26/02 3004

3006 ~ Show Events

ID	Date	Time	Event	User ID	Client ID
253	11/11/02	9:55:58	Login Failure: User demo1	0	0
254	11/11/02	9:56:09	Login Failure: User demo1	0	0
255	11/11/02	9:56:28	Login Failure: User demo1	0	0
256	11/11/02	9:56:39	Login Failure: User kzjones	0	0
257	11/11/02	9:56:54	Login Failure: User kzj	0	0
258	11/11/02	9:57:18	Login Failure: User kzj	0	0
259	11/11/02	9:57:54	Login Failure: User kzjones	0	0

3008 3010 3011 3012 3014 3016

FIG. 25

26/31

3100

Track User Sessions and Hits - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media

Address <http://sitedevelopment.geoneering.com/e/essmenu.html?stateInfo=eLHcEjtacBbdajYq8822> | 47 | Go | Links

BRYANT
CONSULTANTS

1802 ~ [ADMIN MAIN MENU]
314 ~ [LOG OUT]

Session and Hit Tracking

3102 ~ Choose A Report ☒

From Date: 11/26/2002 ~ 3104 End Date: 11/26/2002 ~ 3106

From Time: 00:00:00 ~ 3108 End Time: 10:57:23 ~ 3110

3112 ~ Submit Request

Notes:
 *When listing Sessions, do not request more than about a day at a time.
 **When listing Hits, do not request more than an hour or two.

[ADMIN MAIN MENU] [LOG OUT]

FIG. 26




FIG. 27

18634.0111

REPLACEMENT
SHEET

27/31

28/31

Site Administration - Microsoft Internet Explorer				
File Edit View Favorites Tools Help				
Back Forward Stop Search Favorites Media Print View Source Go Links				
Address http://sitedevelopment.geoneering.com/e/sessiontrace.html?sessionid=eLHcEjtacBbdajYq8833&stateInfo=eLHcEjtacBbdajYq8833 59				
Hit #	Date & Time	Object Run	Query	Cookies
1	11/26/02 - 10:37:00	signup	GET:	valuedGuest = Yes 010
2	11/26/02 - 10:37:50	login	GET: stateInfo = eLHcEjtacBbdajYq8833 1	valuedGuest = Yes 010 safeSessionID = eLHcej
3	11/26/02 - 10:38:07	signup	GET:	valuedGuest = Yes 010 safeSessionID = eLHcej
4	11/26/02 - 10:38:57	login	GET: stateInfo = eLHcEjtacBbdajYq8833 3	valuedGuest = Yes 010 safeSessionID = eLHcej
5	11/26/02 - 10:39:29	login	POST: stateInfo = eLHcEjtacBbdajYq8833 4 adminuser = demo password = demo runAction = Log In	valuedGuest = Yes 010 safeSessionID = eLHcej

FIG. 28

3300




FIG. 29A




FIG. 29B




FIG. 30




FIG. 31

31/31